

Maxigard™ A1000/ A1000C Spare Parts

PN 1129 Sensor With 10' Cable



PN 1130 Sensor Mounting Bracket




PN 1136 Magnetic Disc (16 Magnets)



PN 1393 PVC Sensor With 10' Cable (A1000C)



PN 1394 Sensor Mounting Bracket (A1000C)




PN 1392 PVC Magnetic Disc / 16 Magnets(A1000C)



PN 1132 Explosion Proof Sensor With 10' Cable




PN 1134 Mounting Bracket For XP Sensor




PN 1315 A1000 Power Supply Circuit Board



PN 1325 Calibration Circuit Board



PN 1320 Relay (DTDT-10 amp)



**PN 1726 A1000 Circuit Board Assembly
(PN1315, PN1325, PN1320)**

